Inspection Report

Name of Work	: Construction of Class Room at Ramachandrapura in Ward No. 10 (Doddabommasandra), Vidyarnyapura Sub Division.
Work Order	: EE/BTP/BBMP/E-PMT-07(13906)/WO/198/2014-15 Dated: 08.01.2015
Agency	: A. Krishna Reddy
B.R. No & Date	: 26/2015-16 Dated: 30.04.2015
Bill Amount	: 20,98,081.42
Job Code	: 010-15-000031
P. Code	: P-3055
Date of Inspection	: 15-06-2016.

The above said work Construction of class Room at Ramachandrapura in Ward no 10 (Doddabommasandra), Vidyarnyapura Sub Div. was found to be as per the Concerned Ward Engineer.

The work is inspected by me along with the Concerned Ward Engineer.

The work done is Satisfactory

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Jadhav
AE

Sketch Showing the Work of Construction of Class Rooms at Ramachandrapura in Ward No. 10 (Doddabommasandra), Vidyarnyapura Sub Division.



MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Sadha
AE

Photo Showing the Work of Construction of Class Rooms at Ramachandrapura in Ward No. 10 (Doddabommasandra), Vidyarnyapura Sub Division.

Sadhna
AE

MANJUNATH. K
DOM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Photo Showing the Work of Construction of Class Rooms at Ramachandrapura in Ward No. 10 (Doddabommasandra), Vidyarnyapura Sub Division.

Jadhav
AE

MANJUNATH. K
DOM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Photo Showing the Work of Construction of Class Rooms at Ramachandrapura in Ward No. 10 (Doddabommasandra), Vidyarnyapura Sub Division.

Sudha
AE

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT